# OPL2LPT and OPL3LPT : Compatibility improvement fix

OPL2LPT and OPL3LPT run fine on most computers, but a few customers reported incompatibility with their parallel port. The following PC models so far, were found to be incompatible :

- PCJr
- PS/2 P70
- Dell 386sx-16
- Nec 386sx-16

This incompatibility can be easily and 100% fixed by adding a 1k pull up resistor to the strobe line. From now on, to maximize compatibility, OPL3LPT assembled PCB's will be sold with this modification already implemented. OPL2LPT solder kits will also include an additional 1k resistor.

Please find the photos below showing how you can add this 1K resistor, if needed.

Happy DOS gaming !

Serge

https://www.serdashop.com/Contact